

NEW RB CONFIG UPDATE, THAT CONTAIN MINOR BUG FIXES:

RB CONFIG 1.26

- FIX COMMUNICATION TIMING ISSUE WHEN CONNECTED TO SE7EN OR M28, WHICH COULD MAKE THE FIRMWARE UPDATE TO TERMINATE OR FAIL.

THIS UPDATE DOES NOT EFFECT MKVI USERS.