

NEW M28 AND SE7EN FIRMWARE UPDATE, THAT CONTAIN MINOR BUG FIXES:

M28 FIRMWARE V2.3

- SPEED IMPROVEMENT - BETTER INTEGRATION WITH SE7EN
- BETTER HANDLING OF SSD2
- IMPROVED PLANNER
- IMPROVED PICTURE HANDLING
- RESOLVES THE ISSUE WITH TEMPERATURE SENSOR "MISSING" AFTER FW UPDATE

SE7EN FW UPDATE TO VERSION 1.53

THE FIRMWARE UPDATES MADE TO THE M28 REQUIRES UPDATES TO THE SE7EN FIRMWARE. EVEN IF YOU DO NOT USE/INTEND TO USE A M28 COMPUTER WITH YOUR SE7EN, IT'S ALWAYS RECOMMENDED THAT YOU UPDATE YOUR SE7EN TO THE LATEST FIRMWARE VERSION AVAILABLE.

MINOR BUG FIXES

THIS UPDATE DOES NOT EFFECT MKVI USERS.